

Tiverton & Tilstone Fearnall Parish Council - Outstanding Highways Issues					April 2019
Highways Issues Reported through CW&C Fault Reporting System					
In order for the Parish Council to track the progress of a Highways Fault it must be reported via the CW&C Highways Reporting System and an Enquiry Number obtained.					
Date Reported	Enquiry No	Issue Reported	Location	Comment	Status
12-Apr-19	4863336	2 Potholes	Huxley Lane - opposite Tiverton Hall & TH Cottages		
12-Apr-19	4863335	Road surface damage to recently resurfaced road	Crib Lane - near SLOW marking close to Huxley Lane	Resubmitted because erroneously marked as complete	
12-Apr-19	4863334	Road surface damage	Huxley Lane - opposite Castle View		
12-Apr-19	4863333	Pothole	Huxley Lane - opposite Hilly Bank		
12-Apr-19	4863327	Pothole	Huxley Lane - opposite 1 Castle View		
12-Apr-19	4863326	Road surface damage	Huxley Lane - opposite Fir Tree Cottage		
12-Apr-19	4863325	Road surface damage right across the road	Huxley Lane - opposite Rose Cottage		
12-Apr-19	4863324	Cracking/potholes on road surface	Huxley Lane - Village Hall thro to the Stables Cottage		
12-Apr-19	4863322	Damage to fencing around grassed area	Diagonally opposite 4863320	Damage caused by vehicles turning during A49 road closure	
12-Apr-19	4863321	Damage to Huxley Lane street sign	Junction of Huxley Lane and A49	Damage caused by vehicles turning during A49 road closure	
12-Apr-19	4863320	Damage to fencing around grassed area	South of Huxley Lane at the junction with the A49	Damage caused by vehicles turning during A49 road closure	
1-Sep-18	4842757	Road Surface Cracking & pothole	Outside Ivy Cottage, Huxley Lane near to village green	Update made (12/4/19) because of further deterioration	
14-Apr-19	4863395	Concrete containers on the verge	Huxley Lane, Tiverton	Discussed at Meeting held Oct 17. Re-reported June 18 as now planted with flowers. Reported again on 14/4/19	
Other Highways Issues					
2018		On going concerns regarding speeding down the A49 in particular the stretch of road between Huxley Lane and Beeston Brook Railway Bridge. Vehicles are regularly observed exceeding the 30mph speed limit and there are frequent bridge collisions by high side vehicles.		Speed monitoring and discussions with the police and CW&C Highways. Improved signage and better speed enforcement (camera) requested.	
2018		Concerns voiced by a number of residents regarding speeding on Huxley Lane outside the 30mph zone, particularly where the Sandstone Trail crosses the road where there is a dip in the road and cars can appear with little or no warning.		Unlikely to be any speed limit change, but warning signs are promised by CW&C Highways.	